# Completion Report

| | | |
|---|---|---|
| 1 | Name of Wok | Reserve Fund For Emergency Works Ward No 15 (Depot collection for filling pot holes and Removing and resetting of covering slabs and removing of debries in Dasarahalli Ward No 15 T.Dasarahalli Sub Division) |
| 2 | Sanctioned Estimate No.& Date | CE/DZ/TS/ 05 /2020-21, Dt.06.05.2020 |
| 3 | Head of Acount which is Chargeable | P-1771 |
| 4 | Enstrument Order No. & Date | EE/DD/WO/80/20-21, Dt.03.08.2020 |
| 5 | Name of Contractor | D V Kumar |
| 6a | Time Stipulated for Completion of work | 90 days |
| b | Delay in execulation of work | – |
| 7 | Measurement recorded in MB | 1670/10-11 |
| | Page No | 166924-939/1 |
| 8 | check Measurment of the Asst | |
| | Exe. Eng./ Exe.Eng. On | |
| 9 | Name of the Office / Official | Asst.Executive Enginner |
| | incharge of the work | T.Dasarahalli Sub Division |
| 10 | a)Assistant Engineer | ARCHANA |
| | b) Asst. Exe. Engineer | M B Jayakumar |

| Sanctioned Estimate amount | Amount claims as per actually vide as per bills | Excess | Savings (Rs) |
|---|---|---|---|
| 10.00 Lakhs | 890035.00 | – | 109965.00 |

1) Certified that the above work has been Completed within the stipulated time nited in the

2) Certified that the Contractor has delayed and completed the work for which necessary fine recovered

3) Certified that the above work has been executed by the contractor satisfactorily

SISTANT ENGINEER

ASSISTANT EXECUTIVE ENGINEER

EXECUTIVE ENGINEER
Bruhat Bengaluru Mahanagara Palike
Dasarahalli Division, Bengaluru-73.

Scanned by CamScanner